

International Road Dynamics Inc.Site Service Sheet

Clear

						System Type:	WIM Bend	ling Plate
Date: <u>6/23/2010</u>	State:	AZ		Location	Buckey I-1	10 mp 109		
Job #: 11013			-		Buokoyi			
	Long	4	Long		Long		Long	
Loons	Lane - Lead	1 Trail	Lane - Lead	Trail	Lane - Lead	Trail	Lane - Lead	Trail
Loops Resistance		3.8 ohms	Leau	Hall	Leau	Hall	Leau	Hall
Leakage	4.5 011118	3.0 011118						
Inductance	0.6 nF	0.7 nF						
Frequency	0.0	017 111						
	Lane -	1	Lane -	T	Lane -	_	Lane -	
Weighpads	Lead	Trail	Lead	Trail	Lead	Trail	Lead	Trail
Supply	987 ohm							
Signal	881 ohm							
Shield	infinite	infinite						
Zero Pt	0.6 mV	0.4 mV						
Serial #								
Piezos	Lane -		Lane -		Lane -		Lane -	
Amplitude	Lanc -		Lanc -		Lanc		Lanc -	
Capacitance								
Resistance								
				•				
System			Temp Sensor			-		
A/C Service						1		
Power Supply]		
Solar Panel	13.4 VDC							
Back-Up								
System Input								
Modem Power								
Phone off hook								
Phone on hook								
Technician:	B. Knight				_Date:	6/23/2010		





















